


PDZ18b North Anglesey - Twyn Cliperau to Trwyn Cwmrwd

ID		Location	Type	Feature	Issue associated with feature	FCD Issue	Affect Policy	Benefits/Why is issue important	Scale	Issue Type/ Theme	Who are the beneficiaries	Is this enough of this benefit	Potential for substitution	Objectives
1560	H140	Llanbagrig Point	Listed Building	Church of St Padrig Anglesey LB	Close to cliff edge on a small headland, may be lost to cliff erosion	Yes	Yes	Listed Buildings	National	H	National Community	No	No	To prevent disturbance or deterioration to the structure and its setting and to maintain access
1561	F366	Llanbadrig	Listed Building	Church and graveyard	Situated on the edge of a cliff, may be lost with coastal recession	Yes	Yes	Listed Buildings	National	H	National Community	No	No	To prevent disturbance or deterioration to the structure and its setting and to maintain access
1562	F365	Porth Wen	Listed Building	Disused kiln, works	Close to cliff edge, may be lost to coastal recession in the future	Yes	Yes	Listed Buildings	National	H	National Community	No	No	To prevent disturbance or deterioration to the structure and its setting and to maintain access
1563	H139	Llanlleiana Head	SAM	Dinas Gynfor Hill fort SAM	This SAM covers the headland of Porth Llanlleiana and is likely to experience issues with cliff erosion	Yes	Yes	Scheduled Monument (historical)	National	H	National Community	No	No	To prevent disturbance or deterioration to the site and its setting
1564	H138	Porth Wen	SAM	Porth Wen brickworks SAM	The disused brickworks are situated to the north east of Porth Wen, likely to have some loss of land due to coastal erosion	Yes	Yes	Scheduled Monument (historical)	National	H	National Community	No	No	To prevent disturbance or deterioration to the site and its setting
1565	F364	Porthlechog	Coastal Road	Coastal road and properties	Close to the shore, likely to experience issues in the future with SLR	Yes	Yes	Dwellings and access	Local	HA	Local Community	No	No	Maintain access and prevent loss of properties due to SLR
1567	F362	Amlwch	Harbour / Marina	Harbour	Risk of flooding in the future	Yes	Yes	Busy port for pilot boats and fishing boats	Regional	C	Regional Community	No	No	Maintain function of harbour
1568	H137	Amlwch	Listed Building	Many Anglesey listed buildings	Situated near the coast, seaward of the coast road within an inlet. These properties may experience issues with SLR	Yes	Yes	Listed Buildings	National	H	National Community	No	No	To prevent disturbance or deterioration to the structure and its setting and to maintain access
1569	F361	Amlwch	Listed Building	Listed buildings	Close to the coast at risk of being lost to SLR	Yes	Yes	Listed Buildings	National	H	National Community	No	No	To prevent disturbance or deterioration to the structure and its setting and to maintain access
1570	F360	Porth Eilean	Beach	Beach and Slipway	Sandy bay has required intervention measures to prevent erosion in the past due to the wave climate in the area as a result of the orientation of port llynas. Likely to worsen in the future with SLR, slipway likely to be lost	Yes	Yes	Beach access	Local	R	Local Community	No	No	Maintain access
1571	H136	Port Llynas	Listed Building	Point Llynas lighthouse and telegraph station, Anglesey LBs	Although this feature is situated on a rocky headland, about 30m from cliff edge, there is a risk of some loss of this property due to cliff erosion	Yes	Yes	Listed Buildings	National	H	National Community	No	No	To prevent disturbance or deterioration to the structure and its setting and to maintain access
1572	F359	Port Llynas	Boating / Shipyards	Lighthouse	Although located on a headland, fairly close to cliff edge (30m) maybe at risk in the future	Yes	Yes	Navigation	Regional	HA	Regional Community	No	Yes	Maintain function of lighthouse for navigational purposes and heritage value
1573	F290/E064	Morfa Dulas	SSSI	Coed y gell and Morfa Dulas SSSI	This SSSI forms the tip of the spit on the southern side of the Afon Gich estuary, may have flooding issues in the future	Yes	Yes	National nature conservation interest (ecology / habitat - woodland, dune grassland and saltmarsh)	National	E	National Community	No	No	To maintain or enhance the condition or integrity of the SSSI and interest features within the context of a dynamic coastal system
1574	F358	Dulas Bay	Properties	Coastal Properties	At risk if circulatory current causes a change to the dynamics of this area (see SMP1)	Yes	Yes	Dwellings	Local	HA	Local Community	No	Yes	Prevent loss of properties due to erosion

Yes





0 1 2 4 Kilometres

511